

Munoz, Rick

From: Munoz, Rick
Sent: Thursday, December 18, 2014 5:39 PM
To: Cargill, Scott
Cc: Munoz, Rick
Subject: RE: Applus RTD - Valley Ind. Xray - QISI
Attachments: APPLUS IDAHO FALLS .pdf

Scott,

I have attached the clear inspection report documentation for the site inspection at 1550 Jones Street in Idaho Falls on December 3-4. David Hooper was most courteous and helpful in helping me get through the document review. If you have any questions on the document, please feel free to contact me on my cell phone. Happy Holidays!!

Regards,

Rick Muñoz
Nuclear Materials Inspector
U.S. Nuclear Regulatory Commission, Region-IV
1600 East Lamar Boulevard
Arlington, Texas 76011-4511

Office: (817) 200-1220
Cell: (512) 773-8520
Fax: (817) 200-1188
Email: rick.munoz@nrc.gov



The information contained in this message may be privileged and/or confidential and protected from disclosure. If the reader of this message is not the intended recipient, or an employee or agent responsible for delivering this message to the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please notify the sender immediately by replying to the message and deleting the material from any computer.

Note: Any views or opinions presented in this message are solely those of the author and do not necessarily represent those of the Nuclear Regulatory Commission, Region-IV or the Nuclear Materials Safety Branch-A. All e-mails are subject to monitoring and archival.

Finally, the recipient should check this message and any attachments for the presence of viruses. The Nuclear Regulatory Commission accepts no liability for any damage caused by any virus transmitted by this e-mail.

From: Cargill, Scott [<mailto:Scott.Cargill@applusrtd.com>]
Sent: Monday, December 15, 2014 10:47 AM
To: Munoz, Rick
Cc: Miskell, Doug
Subject: Applus RTD - Valley Ind. Xray - QISI

Rick,

I don't know if this helps or hinders your audit but after talking to the boys back east, it has been decided to remove the Idaho falls field station from the license. In short they haven't used the facility to actually store material in over a year. They do occasionally do work in Idaho, but the crew and the source comes out of our Washington office to perform the work.

I have submitted the amendment request to region IV to remove the site.

Kind regards,

Scott Cargill

Corporate Radiation Safety Officer
1001 - Valley Industrial Bakersfield

T +1 661 695 3197

T Internal 212 3197

F +1 661 393 2143

M +1 661 979 1682

E Scott.Cargill@applusrtd.com

I www.ApplusRTD.com



Applus RTD USA West
332 East Norris Road, Suite 3
Bakersfield, California 93308
United States of America

This e-mail is privileged, confidential and contains private information.
Any reading, retention, distribution or copy of this communication by
any person other than its intended recipient, is prohibited.

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:

Applus RTD USA, Inc.
6201 Knudsen Drive
Bakersfield, California 93308
Location: 1550 Jones Street, Unit F, Idaho Falls, ID

REPORT NO: 03038291/2014-002

2. NRC/REGIONAL OFFICE

U.S. Nuclear Regulatory Commission - Region IV
1600 East Lamar Boulevard
Arlington, Texas 76011-4511

3. DOCKET NUMBER

030-38291

4. LICENSE NUMBER

04-29076-02

5. DATES OF INSPECTION

December 1-18, 2014

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:



- ☒ 1. Based on the inspection findings, no violations were identified.
- ☐ 2. Previous violation(s) closed.
- ☐ 3. The violations(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy to exercise discretion, were satisfied.

☐ Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

- ☐ 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	R. Rick Muñoz		12/18/2014
BRANCH CHIEF	G. Michael Vasquez		1/28/15

☐ Non-Public ☐ Sensitive – Security-Related

☒ Public

☒ Non-Sensitive